


FIG. 1



2/34

FIG.2






FIG.3




3/34

FIG.4




4/34

FIG.5




5/34

FIG.6




6/34

FIG.7




7/34

FIG.8



8/34

FIG.9



9/34

FIG.10






FIG.11



11/34

FIG.12



12/34

FIG.13




FIG.14A






FIG.14B



14/34

FIG.16



15/34

FIG.17A





FIG.17B



16/34

FIG.18






FIG. 19






19/34

FIG.21

TYPE OF SERVICE (ToS)	PRIORITY (LEVEL)
000	-
001	-
010	M
011	-
100	H
101	-
110	-
111	-

20/34

FIG.22



21/34

FIG.23




FIG.24





FIG. 25



24/34

FIG.26





FIG.27



25/34

FIG.28






FIG.29





27/34

FIG.31







FIG.32






29/34

FIG.34



30/34

FIG.35



31/34

FIG.36






FIG.37



32/34

FIG.38



33/34

FIG.39




FIG.40





FIG. 41A

FIG. 41B



EVEN IF THE RECEIVER TERMINAL FALSELY REPORTS THAT M#8 HAS
 CORRECTLY BEEN RECEIVED, THE MONITOR APPARATUS IS UNABLE
 TO DETECT THE FALSENESS OF THE REPORT BECAUSE IT IS UNABLE
 TO DETECT ANY PACKET LOSS UP TO THE RECEIVER TERMINAL

THE MONITOR APPARATUS INTENTIONALLY
 DISCARDS A PACKET TO DETECT THE FALSENESS
 OF A REPORT FROM THE RECEPTION TERMINAL